



							
SW-500DH-380V	380 V	40 W	300 °C	3,6 W (6 pcs)	3 Kg/cm	500 mm	170 / 260 Kg

SW-500DH-380V

OB8013



Continuous belt fusing machine. Width of belt: 500 mm. Pneumatic pressure. Side opened machine. Digital control of temperature. Includes stand with 4 wheels. 380 V.

RETURN

OB8003A



Return cooling device for SW-500DH.

SW-500DH-380V

OB8013



Máquina de termofijar de cinta continua de 50 cm de ancho abierta por un lado. Incorpora 2 rascadores giratorios, mesa para preparación del trabajo y bancada con ruedas. Presión neumática, consumo 3 KW a 380 V trifásica.

RETURN

OB8003A



Mecanismo de retorno y enfriamiento adaptable para SW-500DH.